

ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

Date: 09.09.03	Job No.: 00269	ADR Yes/No: N	ADR Date:		ECN #: 09- 658
Product No.: D130-787		Created By: KB	Approved By:		
Product Name: TAS Installation		Checked By: <u> </u>	General Manager Approval:	NA	

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	09-09-10
Production Engineering Coord	Y	DO/EC	09-09-10
Production Document Control	Y	BG	09-09-10
Customer Technical Support	N		

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	Y	SW	09-09-10
Customer Order Processing	N		

Reason for Change: Add quantity 2 of P/N 190113 BNC right angle connector to D130-787-013 Kit.
Quantity of P/N 190109 TNC right angle connector incorrect. Quantity of P/N 190109 TNC right angle connectors in D130-787-013 Kit should be 10 instead of 4.

Documents Affected:

DSI 9479 REV. A
MDL-D130-787 REV. C

PARTS MUST COMPLY **PREVIOUS PARTS SATISFACTORY**

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	Y	SW		09-10-09
2	Notify Eurocopter France	N			
3		N			

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N	SW		
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		09-09-10
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09-09-09
10	Update Controlled PDF Files	Y	KJ		09-09-09
11	Update Master Document List (MDL)	Y	KB	MDL-D130-787 REV. C	09-09-09
12	Update Document Record (DR)	Y	KJ	Rev. L	09-09-09
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	N			
16	Update / Verify ARC Database	N			
17	Create / Update Change Record Form	N			
18	Create / Update PPP's	N			
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ		09-09-09
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09-09-09
22					
23					

Description / Action:

RECOMMEND PUTTING 2x D130-787-013 KITS IN STOCK
UPDATE ROUTING/ESTIMATE/BOM FOR D130-787-013 TO MATCH DSI 9479.
ENSURE ALL D130-787-013 GOING INTO STOCK INCLUDE EXTRA CONNECTORS PER DSI 9479
ENSURE EXTRA CONNECTORS ARE SHIPPED TO PAPILLON / BLACKMOUNTAIN AVIONICS ASAP.

ECN Verified & Complete: NP

Date: 10/15/20

Under Review Notification

Raised By: K. Barton
Date: 09.09.03

Product #: D130-787-013
Product Name: EC-130 TAS Installation.

Description of issue:

Quantity of P/N 190109 TNC right angle connector incorrect. Quantity of P/N 190109 TNC right angle connectors in D130-787-013 Kit should be 10 instead of 4.

Add quantity 2 of P/N 190113 BNC right angle connector to D130-787-013 Kit.

DSI 9479 to be released shortly on ECN 658.

Distribution:	General Manager Production Manager Director Quality Assurance Design Manager Chief Engineer	Production Engineering Coordinators Quality Assurance Coordinator Quality Control Coordinator Order Processing Customer Technical Support	Engineering Project Managers Engineering Clerk Marketing
----------------------	---------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------